



July 10, 2019

TECHNICAL DATA REPORT

See SDS for complete safety/technical data



VAPCO PART NO.

Part Number GB-LC Size 45 lb cylinder

GOLDEN BEAR

ADHESIVE/ SEALANT

DESCRIPTION

GOLDEN BEAR is specially formulated to provide a versatile and convenient means to bonding paper, cloth, wool, metal, foam, rubber, plastic insulation and many other industrial items. It dries to a slightly tacky, permanently flexible film having excellent physical properties and exceptional resistance to aging. Industrial applications include boxing, taping, knife edging, lamination of foamed products, insulation, aluminum building boards, furniture and automotive upholstery, etc. Volatile Organic Content: 2 g/L.

FEATURES AND BENEFITS

- Easy to Apply
- Permanent or Temporary Bonding

SPECIFICATIONS

Appearance: Clear to Slightly Hazy Yellow/Amber Spray | **Odor:** Solvent odor | **Flammability:** Extremely Flammable Gas | **Vapor Density (AIR=1):** > 1 @ 77°F (25°C) | **Evaporation Rate:** > 3 Fast | **Specific Gravity (H2O=1):** 0.84 @ 77°F (25°C) | **Solids:** 43% | **Solubility in Water:** Immiscible | **Volatility Including Water (%):** 57% | **Volatile Organic Content:** 2 g/L.

LABEL INFORMATION

DIRECTIONS: Keep cylinder off concrete floor during freezing temperatures. For best results use at temperatures between 60°F to 90°F. Extinguish and/or remove all ignition sources. Work area should be well ventilated. Make sure all surfaces to be sprayed are clean and free from debris, dust, dirt, grease, etc. Try gun on a test surface to make sure adhesive is flowing. Hold spray gun 8-10 inches from surface to be sprayed. Avoid buildup of adhesive or bubbles. Edges of spray pattern should overlap giving consistent coverage over surface. Apply fiberglass insulation after 15 seconds. For foil lined insulation, wait at least 1 minute before applying.

DANGERS: Read and understand the product's label and Safety Data Sheet. Extremely flammable gas. Contains gas under pressure. May explode if heated. Causes skin and eye irritation. May cause drowsiness or dizziness. May cause damage to central nervous system through prolonged or repeated exposure. May be fatal if swallowed and enters airways. Keep away from heat, sparks, open



Health	1
Flammability	3
Reactivity	1
Personal	X



First Aid Measures

Inhalation: Move to fresh air. If breathing is difficult, administer oxygen. If not breathing administer artificial respiration. **Seek medical attention if irritation persists.**

Skin contact: Wash thoroughly with soap and water.

Eye Contact: Remove contact lenses. Flush with water for at least 15 minutes. **Seek medical attention if irritation persists.**

Ingestion: Rinse mouth with water. Do NOT induce vomiting. **Seek immediate medical attention.**

Precautions

Keep out of reach of children. Keep away from heat, sparks, open flames, and hot surfaces. Leaking gas fire: Do not extinguish, unless leak can be stopped safely. Eliminate all ignition sources if safe to do so. Protect from sunlight. Store in a well-ventilated place. Wash hands thoroughly after handling. Use only outdoors or in a well-ventilated area. Wear safety glasses and chemical resistant gloves when using product.

Storage

Keep out of reach of children. Lock up and store in a cool, dry area. Keep containers tightly closed. Follow label directions.

In Case of Fire

Use dry chemical, carbon dioxide and foam to extinguish fire. Wear NIOSH approved Self Contained Breathing Apparatus with a full face piece operated in a positive pressure demand mode with full body protective clothing when fighting fires.

Disposal

Dispose of in accordance with federal, state, and local regulations. Do not dump in sewers. Wrap container and place in trash collection, do not puncture, incinerate, or reuse container. This product is biodegradable.

CONTAINS

GOLDEN BEAR CONTAINS (CAS#): Methylacetate (79-20-9), Hexane (110-54-3) Mineral Spirits (64742-40-9), Propane (74-98-6)